复制日志

从矿机界面操作

BYTEON
www.byteonminers.com

【复制日志】 日志 -> 状态/矿机/自动调谐/系统-> 复制



导出诊断报告

从矿机界面操作

法一：【诊断报告】日志 -> 符号


BYTEON
BTCOIN MINER
仪表板
监控
仪表板
设置
挖矿
系统
技术支持
固件更新
哈希率
85.13
当前: 85.5 / Theor: 123.4
TH/s
温度
52° – 70°
电路板: 37° – 55°
摄氏度
功率
3669
估计数据
瓦时
错误
0%
0 H/s
性能
预设
3670 watt ~ 120 TH
Autoswitch
Disabled
效率: 43.1 J/TH
PSU: APW121215a
哈希率
温度
范围:
1小时 12小时 24小时
矿池
45.204.13.203:3301
zfg888888.8x148
True
65.5K
1775
0
84
0:00:04
活跃: 30ms
45.204.13.203:3301
zfg888888.8x148
True
65.5K
804
0
42
0:00:14
活跃
风扇
风扇 1
5730 RPM
风扇 2
6000 RPM
风扇 3
风扇 4
诊断报告
日志
状态
矿机
自动调谐
系统
[3.474240@3]- UBIFS (ubi0:0): media format: w4/r0 (latest is w4/r0), UUID 72E9AF03-788A-4791-BCD4-114543295E6E, small LPT model
[3.553584@3]- Removed cp15_barrier emulation handler
[3.553648@3]- Enabled cp15_barrier support
[3.767656@2]- meson6-dwmac ff3f0000.ethernet eth0: fail to init PTP.
[3.769056@2]- IPv6: ADDRCONF(NETDEV_UP): eth0: link is not ready
[5.806900@2]d meson6-dwmac ff3f0000.ethernet eth0: Link is Up - 100Mbps/Full - flow control off
[5.810888@2]- IPv6: ADDRCONF(NETDEV_CHANGE): eth0: link becomes ready
[97.162401@0]s nf_conntrack: default automatic helper assignment has been turned off for security reasons and CT-based firewall rule not found. Use the iptables CT target to attach helpers instead.
[104.024449@3]- meson_uart ff804000.serial: ttyS3 use xtal(24M:1) 24000000 change 0 to 9600
[104.027227@3]- meson_uart ff804000.serial: ttyS3 use xtal(24M:1) 24000000 change 9600 to 115200
[104.046885@3]- meson_uart ff23000.serial: ttyS2 use xtal(24M:1) 24000000 change 0 to 9600
[104.049591@3]- meson_uart ff23000.serial: ttyS2 use xtal(24M:1) 24000000 change 9600 to 115200
[104.069004@0]- meson_uart ff24000.serial: ttyS1 use xtal(24M:1) 24000000 change 0 to 9600
[104.071773@0]- meson_uart ff24000.serial: ttyS1 use xtal(24M:1) 24000000 change 9600 to 115200
[106.648343@0]- meson_uart ff804000.serial: ttyS3 use xtal(24M:1) 24000000 change 115200 to 3000000
[106.651789@0]- meson_uart ff23000.serial: ttyS2 use xtal(24M:1) 24000000 change 115200 to 3000000
[106.660743@0]- meson_uart ff24000.serial: ttyS1 use xtal(24M:1) 24000000 change 115200 to 3000000
[6590.375894@1]- meson6-dwmac ff3f0000.ethernet eth0: fail to init PTP.
[6590.377[illegible]@1]- IPv6: ADDRCONF(NETDEV_UP): eth0: link is not ready
[6593.[illegible]@1]d meson6-dwmac ff3f0000.ethernet eth0: Link is Up - 100Mbps/Full - flow control off
[6[illegible]@1]- IPv6: ADDRCONF(NETDEV_CHANGE): eth0: link becomes ready
日志
自动调谐中
Antminer S19J Pro
aml
PIC
v1.2.6-rc5

BYTEON
www.byteonminers.com

法一：【诊断报告】填写矿机问题后，创建报告并保存



BYTEON
www.byteonminers.com

法二：【技术支持】

BYTEON
www.byteonminers.com

法二：【技术支持】—> 诊断报告



BYTEON
www.byteonminers.com

法二：【技术支持】诊断报告填写矿机问题后，创建报告并保存